

MORTGAGE BANKING GROUP P.O. Box 22352 Milwaukie, OR 97222 503/653-3375

Dept of Environmental Quality

DEGELVED

NORTHWEST REGION

September 24, 1985

Ms. Janet Gilaspie Northwest Regional Office of the Department of Environmental Quality P.O. Box 1760 Portland, Oregon 97207

Re: 2701 Newark Street, Portland, Oregon

Dear Ms. Gilaspie:

In April 1985 I contacted your office regarding the procedures and policies regarding the identification and potential cleanup of hazardous waste on the above-referenced property. Since that time we have worked with Crowley Environmental Services and Patrick H. Wicks, P.E. Consultants in hazardous waste management in Bellvue Washington to identify what, if any, hazards there may be and how that waste could be disposed.

Enclosed is a report prepared by Patrick H. Wicks, P.E. describing his investigation of the site, identification of certain materials and an action plan for the clean-up of those materials whose level of toxicity exceed an amount described by the Environmental Protection Agency.

We are anxious to clean up the entire site, including non-toxic waste, as soon as possible therefore we request your quick approval of the clean up plan. Should you have any questions please do not hesitate to call.

Cordially,

PACIFIC WESTERN BANK

Douglas H. Leeding Senior Vice President

DHL/da

cc: Patrick Wicks Kevin Sheehy

A PACWEST BANK

SEPA

POTENTIAL HAZARDOUS WASTE SITE PRELIMINARY ASSESSMENT PART 2 - WASTE INFORMATION

I. IDENTIFICATION

01 STATE | 02 SITE NUMBER

OR | D050185750

\/ L.1	* •		PART 2 - WASTE	INFORMATION			
. WASTE ST	ATES, QUANTITIES, AN	D CHARACTERIS	STICS				
	TATES (Check all that apply)	02 WASTE QUANTIT	TY AT SITE		RISTICS (Check all Inal ap		0.4515
. Tva SOLID	TA SOLID E. SLURRY		(Measures of waste quantities must be independent)		XA. TOXIC I E. SOLUBLE II , HIGHLY VOLATILE X B. CORROSIVE I F. INFECTIOUS I J. EXPLOSIVE		
ZB, POWDER, FINES ZF, LIQUID C. SLUDGE G. GAS		TONS LINKNOWN CUBIC YARDS UNKNOWN NO. OF DRUMS UNKNOWN		C. RADIOACTIVE C. G. FLAMMABLE C. K. REACTIVE C. PERSISTENT C. H. IGNITABLE C. M. NOT APPLICABLE C. M. NOT APPLICABLE			
I. WASTE T	YPE						
CATEGORY	SUBSTANCE N	AME	01 GROSS AMOUNT	02 UNIT OF MEASURE	03 COMMENTS		
SLU	SLUDGE						
OLW	OILY WASTE		unknown	PCBs disposed/burned on-site			
SOL	SOLVENTS		unknown		Used to clean metals & transfo		transforme
PSD	PESTICIDES			<u></u>		7 11 500	
occ	OTHER ORGANIC CHEMICALS		unknown		Associated with PCBs.		
100	INORGANIC CHEMICALS		unknown		Possible reclamation byproducts		
ACD	ACIDS		unknown	<u> </u>	Mineral ac	ids	
BAS	BASES				G	amolton/ no	70110771 000
MES	HEAVY METALS		unknown	<u> </u>	Secondary	smerter/ rec	covery opera
V. HAZARD	OUS SUBSTANCES (5.0.	Appendix for most frequen	tly cited CAS Numbers)	T		T of CONCENTRATION	06 MEASURE OF CONCENTRATION
1 CATEGORY	02 SUBSTANCE	NAME	03 CAS NUMBER	04 STORAGE/DIS		05 CONCENTRATION	CONCENTRATION
OLW	PCB		1336-35-3	PL.		unknown	
SOL	Organic solve	ents	999	PI		unknown	
MES	Lead compounds		999	PI.		unknown —	
MES	Arsenic compounds		999	PI.		unknown_	
MES	Mercury compounds		999	PI.		unknown	
MES	Zinc compounds		999	PL		unknown	
OCC	Phenols		108-95-2	PI		unknown	
OCC	1,2-dichlorobenzene		25321-22-6			unknown	1
OCC :	Bis-2-ethyl hexyl phtha			PI		unknown	
IOC	Cyanide compounds		999	PL		unknown	
OCC	Furans		999	PL		unknown	
OCC	Dioxins		999	PI.		unknown	
ACD	Mineral Acids		999	P	<u>L</u>	unknown	
							
V FFFDST	OCKS (See Appendix for CAS Nu	π be/3)	_1				
V. FEEDSTOCKS (See Appendix for CAS Numbers) CATEGORY 01 FEEDSTOCK NAME		02 CAS NUMBER	CATEGORY 01 FEEDS		STOCK NAME 02 CAS NUMBER		
FDS				FOS			
FDS				FDS			
FDS				FDS			
rus				FDS	 		

EPA-OOO CERCLIS files; EPA site inspection (1/7/86); USGS 7.5 minute topo-Portland quad; Water Resources well logs. DEQ CERCLIS files, DEQ NW Region files, DEQ Air Quality Files, and DEQ Water Quality files.